

Service & Repair History





Market Value Fair Price

<u>Check Records</u>

<u>Check Records</u>

<u>Check Records</u>



Odometer Records Check

Check Records



VIN: 1GBLP37J9W3311057

Year: 1998 Make: CHEVROLET Model: Motorhome Chassis

Details info. on VIN: 1GBLP37J9W3311057

Year: 1998

Make: CHEVROLET

Body: Incomplete - Motor Home Chassis

Model: Motorhome Chassis

Vehicle type: INCOMPLETE VEHICLE

Made: UNITED STATES (USA)

Weight: Class 5: 16,001 - 19,500 lb (7,258 - 8,845 kg)

Series: Forward Control

Vin: 1GBLP37J9W3311057

Brake System Type: Hydraulic

Engine Number of Cylinders: 8

Displacement (CC): 7400.0

Displacement (CI): 451.57570630101

Displacement (L): 7.4

Engine Configuration: V-Shaped

Fuel Delivery / Fuel Injection Type: Multipoint Fuel Injection

(MPFI)

Other Engine Info: HO

Engine Manufacturer: WRN

Source: Vpic

Error Code: 0

Error Text: 0 - VIN decoded clean. Check Digit (9th position) is

correct

Vehicle Descriptor: 1GBLP37J*W3

Manufacturer Name: GENERAL MOTORS LLC

Plant City: DETROIT

Plant Company Name: GM Truck Group

Plant State: MICHIGAN

Trim2: 1 ton nominal

Trailer Type Connection: Not Applicable

Drive Type: 4x2

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.



SERVICE MAINTENANCE RECORDS

For your Vehicle 1998 CHEVROLET P30

At the Mileage of 55000 mi

Against the VIN 1GBLP37J9W3311057

A QUICK SUMMARY OF YOUR VEHICLE

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

SAFETY RECALLS 2 items

Your vehicle has 2 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

→ <u>View your recall notices here.</u>

WARRANTY STATUS

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.







- If the vehicle is covered.
- If the vehicle is not completely covered.
- If the vehicle is not covered.

UPCOMING ISSUES 2 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

36% 27%

Likelihood of	Likelihood of
Replace Mass Air Flow (MAF) Sensor	Replace Oxygen Sensor(s) (O2S)
\$443	\$223
Cost of repair	Cost of repair
\$341 in parts	\$121 in parts
\$102 in labor	\$102 in labor
Repair difficulty	Repair difficulty
POOR POOR POOR	NORMAL FAIR DOOR DOOR

This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Upgrade your Report

This Get Car History Report is based only on information acquirable by Get Car History as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Get Car History. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 Get Car History. All Rights Reserved.