



Service & Repair History

[Check Records](#)



Accident & Title History

[Check Records](#)



Market Value Fair Price

[Check Records](#)



Odometer Records Check

[Check Records](#)



VIN: 1XPXD49X9BD129116

Year: 2011 Make: PETERBILT Model: 389

Details info. on VIN: 1XPXD49X9BD129116

Year: 2011

Make: PETERBILT

Engine: ISX

Body: Truck-Tractor

Model: 389

Vehicle type: TRUCK

Fuel Type: Diesel

Made: UNITED STATES (USA)

Weight: Class 8: 33,001 lb and above (14,969 kg and above)

Brake System Type: Air

Engine Number of Cylinders: 6

Displacement (CC): 15000

Displacement (CI): 915.3561614209

Displacement (L): 15

Engine Configuration: In-Line

Engine Manufacturer: Cummins

Source: Vpic

Vin: 1XPXD49X9BD129116

Error Code: 0

Error Text: 0 - VIN decoded clean. Check Digit (9th position) is correct

Vehicle Descriptor: 1XPXD49X*BD

Manufacturer Name: PETERBILT MOTORS COMPANY

Plant City: DENTON

Plant Company Name: Peterbilt

Plant State: TEXAS

Trailer Type Connection: Not Applicable

Drive Type: 6x4

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.

[View our Sample Window Sticker](#)

[Get your Windows Sticker](#)





SERVICE MAINTENANCE RECORDS

For your Vehicle 2011 PETERBILT 389
At the Mileage of 45000 mi
Against the VIN 1XPXD49X9BD129116

A QUICK SUMMARY OF YOUR VEHICLE
If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

SAFETY RECALLS 9 items
Your vehicle has 9 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.
→ View your recall notices here.

This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Upgrade your Report

This Get Car History Report is based only on information acquirable by Get Car History as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Get Car History. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 Get Car History. All Rights Reserved.